27
n38t2
78-4: 2

78-4
pt. 2

TECHNICAL REPORT C-78-4

Metz Reference Room

MAINTENANCE AND PRESERVATION OF CONCRETE STRUCTURES

231-36

Report 2

REPAIR OF EROSION-DAMAGED STRUCTURES

by

James E. McDonald

Structures Laboratory

U. S. Army Engineer Waterways Experiment Station
P. O. Box 631, Vicksburg, Miss. 39180

Metz Reference Room
University of Illinois
B106 NCEL
208 N. Romine Street
Urbana, Illinois 61801

April 1980

Report 2 of a Series

Approved For Public Release; Distribution Unlimited

Prepared for Office, Chief of Engineers, U. S. Army
Washington, D. C. 20314

Under CWIS 31553

B106 CEB, University of Illinois

UNIVERSITY OF MICHIGAN

3 9015 08652 9214